WinDarab V7-Shortcuts

Complete list available in WinDarab Wiki

BOSCH

Navigation

←↑↓→	Move crosshairs
Ctrl+←	Scroll log data
Ctrl+→	Scroll log data
+	Zoom in
-	Zoom out
Ctrl+Z	Undo zoom
Ctrl+Space	Time/dist mode
A	Zoom all
F	Zoom fast lap
L	Zoom lap
N	Next lap
P	Previous lap
Z	Zoom menu

Menu Options

Ctrl+A	Select all files
Ctrl+E	Open file
Ctrl+R	Read data

Channels

Space	Set tag
2 Space	Delete tag
.	Blink channel
Ctrl+0	Show Zero line
Ctrl+9	Show Constant line
C	Color
H	Hide/unhide
I	Channel info
Y	Reset Y range
Ctrl+A	Select all channels in area
Ctrl+Shift+A	Select all channels in oscilloscope
Ctrl+Y	Auto Y range
X	Toggle y-axis mode
D	Display options
V	Display/color mode

Display

G	Toggle Grid

File Options

F4	Activate „shift file"
F5	Show settings (measurement element)
F6	Load new config
F7	Save config
F9	Load desktop
F12	Toggle desktop
Insert	Local add menu
Delete	Local delete menu
R	Replace

Views

F1	Help
F2	Add Worksheet
F3	Filter channel list